

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	Rusty Netz Environmental Coordinator					
OGM	Karl Houskeeper Environmental Scientist III					

Inspection Report

Permit Number:	C0070042			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, July 17, 2007			
Start Date/Time:	7/17/2007 9:00:00 AM			
End Date/Time:	7/17/2007 12:00:00 PM			
Last Inspection:	Tuesday, June 12, 2007			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 80 Deg. F.

InspectionID Report Number: 1351

Types of Operations

Accepted by: dhaddock

7/23/2007

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages
---------	----------

152.81
88.78

Mineral Ownership

Federal Underground State Surface County Loadout

✓ Fee☐ Processing☐ Other✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending actions: No pending actions.

Maintenance work on Ponds 005, 006, 009 and several sediment basins has been done.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, July 18, 2007

ran nouskeeper, Environmental

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 17, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	2. Signs and Markers			✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		~	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading ·				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other		П	П	

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 17, 2007

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Pending actions: No pending actions.

2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Maintenance work has been performed on pond 009 and 006. Both ponds have had sediment removed from the interior of the pond which should bring them to approximately a 40% sediment level. Pond 006 and two sediment basins above 006 have been completely cleaned. The next sediment pond inspection should give the exact information on the ponds and their capacities.

7. Coal Mine Waste, Refuse Piles, Impoundments

Mining operations on top of the refuse pile are now taking place on the western side. The track hoe has been repaired and was actively excavating a lift during the inspection. The refuse pile appeared stable, with no visible hazards.

The culvert remnants located on the eastern surface of the refuse pile from the repairs done last year have been smashed and are scheduled to be be removed.